Wood County Board of Developmental Disabilities

PROCEDURE

Procedure #:

02-ALL-ALL-0450 (SF)

Subject:

Power Failure for all Wood County

Board of DD

Effective Date:

02-14-95

Last Revision:

05-26-23

Person Responsible:

Health & Safety Coordinator

Approvals/Date:

Superintendent WCRDD

Date

Department Director

Date

The following definitions will apply:

Secondary Source of Light - May be emergency lighting, flashlight, or generator which produces electricity for emergency lights.

- 1. If a power failure occurs the secondary source of light shall be obtained and activated. Each facility shall have a secondary source of light and staff shall be in-serviced in their location.
 - a. Generators Service and Support Building and Wood Lane School
 - b. Emergency Lighting Service and Support Building, Community Supports Building, and Fairview
 - Flashlights Wood Lane School and all other facilities
- 2. After accounting for all individuals served and staff the supervisor will contact Maintenance On-Call.
- 3. Maintenance On-Call will investigate and determine the problem.
- 4. If the problem cannot be solved and the source of the problem appears to be electrical, Maintenance On-Call will report the power outage to:
- a. For the East Gypsy Lane Road Complex (SSB, WLS, CSB) October 1st March 1st call Hancock Wood 419-257-3241; March 1st September 30th call Bowling Green 419-354-6260 (business hours) or 419-352-1131 (Evenings)
- b. For Bowling Green Homes/Facilities, and Fairview 419-354-6260 (business hours) or 419-352-1131 (Evenings)
- 5. WCBDD: If inclement weather and an evacuation is necessary, please refer to procedure 02-ALL-ALL-0703 (SF).
- 6. Drills will take place quarterly (March, June, September, and December) and documented on form 03-ALL-ALL-0429, including a written analysis for each drill. That form will be completed and forwarded to the Superintendent or Designee.

Forms:

03-ALL-ALL-0429 03-ALL-ALL-0902

tar\procedure\sf0450